

**C10 / C11**

**Level 2.5**

**Repair Documentation**

V 1.0

## **1Introduction**

The product family C1x consists of C10 (GSM-900), C11 (GSM-1800) and C12 (GSM-1900). This manual only deals with the C10 and the C11. If parts or repairs are identical instead of C10 and C11 only C1x is mentioned.

This manual is intended to help you carry out repairs on level 2.5, meaning limited component repairs. Failure highlights are documented and should be repaired in the local workshops.

It must be noted that all repairs have to be carried out in an environment set up according to the ESD (Electrostatic Discharge Sensitive Devices) regulations defined in international standards.

If you have any questions regarding the repair procedures or spare parts do not hesitate to contact our technical support team in Kamp-Lintfort, Germany:

Tel.: +49 2842 95 4666

Fax: +49 2842 95 4302

e-mail: [dominik.schnoor@klf.siemens.de](mailto:dominik.schnoor@klf.siemens.de)

## Table of Contents:

<b>1 INTRODUCTION.....</b>	<b>2</b>
<b>2 13 MHZ OSCILLATOR .....</b>	<b>4</b>
<b>3 FUSE 1A .....</b>	<b>9</b>
<b>4 RINGER CONNECTOR .....</b>	<b>15</b>
<b>5 MOLEX CONNECTOR .....</b>	<b>21</b>
<b>6 18MH COIL .....</b>	<b>25</b>
<b>7 ANTENNA SPRING .....</b>	<b>30</b>

## **213 MHz oscillator**

### **2.1 Affected Units**

**2.1.1 Type:** C10, C11 (different components!)

**2.1.2 Affected IMEIs / Date Codes:** All / All

**2.1.3 Affected SW-Versions:** All

**2.1.4 Fault Code for LSO reporting:** C10: 3OSC  
C11: 3VCX

### **2.2 Fault Description**

#### **2.2.1 Fault Symptoms for customers:**

Network Search  
Handset not logging into network

#### **2.2.2 Fault Symptom on GSM-Tester:**

Frequency error in synchronized mode >90 Hz  
No location update possible

The Oscillator is responsible for generating the 13 MHz reference frequency of the handset. If it is defective, the handset cannot synchronize to the base station anymore.

**2.3 Priority:**

- ☐ ..... Mandatory
- ☐ ..... Repair
- ☐ ..... Optional
- ☐ ..... Not Yet Defined

**2.4 Repair Documentation****2.4.1 Description of procedure:**

For the C10 three different 13MHz oscillators can be used: A TCXO, a VCXO (Both are called Z601 in the placement diagram) and a normal 13 MHz oscillator (Z602).  
The production status handsets all have a normal 13 MHz oscillator placed, no VCXO or TCXO is used.

For the C11 only a VCXO is used.

**2.4.1.1 Diagnosis**

Check the output frequency of the oscillator using the level-2 testing program for C10 / C11.  
Set the „Simulator“ option in the S611.INI file to 0 and restart the program. Start the test. When the program says „Check power and phase of external antenna with your GSM-Tester“, switch the CMD to „LOCAL“ mode and enter the „MODULE TEST“.  
On the CMD display you can see the frequency error of the handset. (Make sure that the CMD is on channel 124, power level 5!)

If the frequency error is higher than 2kHz, the oscillator has to be replaced.

**2.4.1.2 Repair by component change**

Use hot air blower to remove defective oscillator.  
Avoid excessive heat!  
Watch surrounding components!

Resolder new oscillator afterwards.

**2.4.1.3 Repair by SW-Bootng**

Not possible!

#### **2.4.1.4Test**

Retest handset after repair as described above.  
The frequency error must now be < 2kHz.

### **2.4.2List of needed material**

#### **2.4.2.1Components**

**C10:** 13 MHz oscillator  
Part-Number: L36145-F220-Y2

**C11:** VCXO  
Part-Number: L36145-G300-Y21

#### **2.4.2.2 Jigs and Tools**

Hot Air Blower  
Soldering Iron

#### **2.4.2.3Special Tools**

None

#### **2.4.2.4Working materials**

Desolder Wick / Braid  
Solder

### **2.4.3Drawings**




Figure 1: C10 Board 13 MHz Oscillator Side (Top View)




Figure 2: C10 13 MHz Oscillator Placement (Z602) (Top View)




Figure 3: C11 Board VCXO Side (Top View)




Figure 4: C11 VCXO (Z601) Placement (Top View)



### **3Fuse 1A**

#### **3.1Affected Units**

**3.1.1Type:** C10, C11

**3.1.2Affected IMEIs / Date Codes:** *All / All*

**3.1.3Affected SW-Versions:** *All*

**3.1.4Fault Code for LSO reporting:** C10, C11: 3FU1

#### **3.2Fault Description**

##### **3.2.1Fault Symptoms for customers:**

Battery charging not possible

##### **3.2.2Fault Symptom on GSM-Tester:**

This fault cannot be detected with a GSM-Tester

**3.3 Priority:**

- ☐ ..... Mandatory
- ☐ ..... Repair
- ☐ ..... Optional
- ☐ ..... Not Yet Defined

**3.4 Repair Documentation****3.4.1 Description of procedure:****3.4.1.1 Diagnosis**

Check the status of the fuse by measuring its resistance with a multimeter. The fuse is defective if the resistance is higher than 10 ohms.

**3.4.1.2 Repair by component change**

Use soldering iron to remove defective fuse.  
Avoid excessive heat!  
Watch surrounding components!

Resolder new fuse afterwards.

**3.4.1.3 Repair by SW-Booting**

Not possible!

**3.4.1.4 Test**

Retest handset after repair as described above.

The resistance must now be close to zero.

### **3.4.2 List of needed material**

#### **3.4.2.1 Components**

Fuse  
Part-Number: L36145-A820-Y7

#### **3.4.2.2 Jigs and Tools**

Soldering Iron

#### **3.4.2.3 Special Tools**


Multimeter

#### **3.4.2.4 Working materials**

Desolder Wick / Braid  
Solder

**Figure 1: C10 Board 1A Fuse Side**








Figure 3: C11 Board 1A Fuse Side




Figure 4: C11 1A Fuse (F901) Placement (Top View)

## **4Ringer Connector**

### **4.1 Affected Units**

**4.1.1 Type:** C10, C11

**4.1.2 Affected IMEIs / Date Codes:** *All / All*

**4.1.3 Affected SW-Versions:** *All*

**4.1.4 Fault Code for LSO reporting:** C10, C11: 3RIC

### **4.2 Fault Description**

#### **4.2.1 Fault Symptoms for customers:**

Problems with the handset ringer. No ringer tone audible.

#### **4.2.2 Fault Symptom on GSM-Tester:**

Handset fails ringer test.

### **4.3 Priority:**

- ☐ ..... Mandatory
- ☐ ..... Repair
- ☐ ..... Optional
- ☐ ..... Not Yet Defined

## **4.4 Repair Documentation**

### **4.4.1 Description of procedure:**

The connector B1 is connecting the main board of the C1x with the piezo ringer through a two pin cable.

#### **4.4.1.1 Diagnosis**

Visually check the connector. Watch for bent contacts and dry joints.

#### **4.4.1.2 Repair by component change**

Resolder dry soldering joints.

If the connector is physically damaged use hot air blower or wick to remove defective connector.

Avoid excessive heat!

Watch surrounding components!

Resolder new connector afterwards.

#### **4.4.1.3 Repair by SW-Booting**

Not possible!

#### **4.4.1.4 Test**

Retest handset after repair.



**4.4.2 List of needed material****4.4.2.1 Components**

Ringer Connector C1x:  
Part-Number: L36334-Z97-C43

**4.4.2.2 Jigs and Tools**

Hot Air Blower  
Soldering Iron

**4.4.2.3 Special Tools**

None

**4.4.2.4 Working materials**

Desolder Wick / Braid  
Solder  
Flux

**4.4.3 Drawings****Figure 1: C10 Board Ringer Connector Side**




Figure 2: C10 Ringer Connector Placement (Top View)




Figure 3: C11 Board Ringer Connector Side





Figure 4: C11 Ringer Connector Placement (Top View)



## **5Molex Connector**

### **5.1Affected Units**

**5.1.1Type:** C10, C11

**5.1.2Affected IMEIs / Date Codes:** *All / All*

**5.1.3Affected SW-Versions:** *All*

**5.1.4Fault Code for LSO reporting:** C10, C11: 3MOC

### **5.2Fault Description**

#### **5.2.1Fault Symptoms for customers:**

Battery charging not possible.  
Problems with external loudspeaker or microphone  
when using a car kit.  
Network search when using the external antenna.  
Problems with data accessories.

#### **5.2.2Fault Symptom on GSM-Tester:**

Output power problems on the external antenna only

### **5.3Priority:**

- ☐ ..... Mandatory
- ☐ ..... Repair
- ☐ ..... Optional
- ☐ ..... Not Yet Defined

## **5.4 Repair Documentation**

### **5.4.1 Description of procedure:**

#### **5.4.1.1 Diagnosis**

Visually check the bottom connector. Watch for dry joints or a broken charging pin.

#### **5.4.1.2 Repair by component change**

Use hot air blower remove defective bottom connector.  
Avoid excessive heat!  
Watch surrounding components!

Resolder new bottom connector afterwards.

#### **5.4.1.3 Repair by SW-Booting**

Not possible!

#### **5.4.1.4 Test**

Retest handset after repair.

### **5.4.2 List of needed material**

#### **5.4.2.1 Components**

Bottom Connector C10, C11  
Part-Number: L36334-Z93-C244

#### **5.4.2.2 Jigs and Tools**

Hot Air Blower  
Soldering Iron

### 5.4.2.3 Special Tools


None

### 5.4.2.4 Working materials


Desolder Wick / Braid  
Solder

### 5.4.3 Drawings


Figure 1: C10 Board Bottom Connector Side



**Figure 2: C11 Board Bottom Connector Side**



**Figure 3: C1x Bottom Connector (X203) Placement (Top View)**





## **618µH Coil**

### **6.1 Affected Units**

**6.1.1 Type:** C10, C11

**6.1.2 Affected IMEIs / Date Codes:** *All / All*

**6.1.3 Affected SW-Versions:** *All*

**6.1.4 Fault Code for LSO reporting:** C10, C11: 3COI

### **6.2 Fault Description**

#### **6.2.1 Fault Symptoms for customers:**

Loud humming noise in loudspeaker.

#### **6.2.2 Fault Symptom on GSM-Tester:**

Handset fails with loud humming noise in echo loop.

### **6.3 Priority:**

- ☐ ..... Mandatory
- ☐ ..... Repair
- ☐ ..... Optional



..... Not Yet Defined

## **6.4 Repair Documentation**

### **6.4.1 Description of procedure:**

#### **6.4.1.1 Diagnosis**

The 18 $\mu$ H coil is used in the step up converter which is generating a 6.0 V supply voltage for the power amplifier out of the 2.8V battery voltage.

If the coil is mechanically damaged (broken) it produces heavy interference with the acoustical elements of the C1x resulting in a loud humming noise in the earpiece.

A broken coil can easily be diagnosed by trying to move it with two fingers. If it moves, the core is broken and the coil has to be replaced.

#### **6.4.1.2 Repair by component change**

Use hot air to remove defective coil.  
Avoid excessive heat!  
Watch surrounding components!!

Resolder new coil afterwards

#### **6.4.1.3 Repair by SW-Booting**

Not possible!

#### **6.4.1.4 Test**

Retest handset after repair by checking the audio quality with the echo loop of the testprogram.

**6.4.2 List of needed material**

**6.4.2.1 Components**    **18 $\mu$ H Coil**  
Part-Number: L36151-F5183-M

**6.4.2.2 Jigs and Tools**

Soldering Iron  
Hot Air Blower

**6.4.2.3 Special Tools**


None

**6.4.2.4 Working materials**

Desolder Wick / Braid  
Solder

## 6.4.3 Drawings


Figure 1: C10 Board 18 $\mu$ H Coil (L201) Side




ICP CD ST

D. Schnoor  
08/98

**Figure 3: C11 Board 18 $\mu$ H Coil (L201) Side**



**Figure 4: C11 18 $\mu$ H Coil (L201) Placement (Top View)**



## **7Antenna Spring**

### **7.1Affected Units**

**7.1.1Type:** C10, C11

**7.1.2Affected IMEIs / Date Codes:** *All / All*

**7.1.3Affected SW-Versions:** *All*

**7.1.4Fault Code for LSO reporting:** C10, C11: 3ANS

### **7.2Fault Description**

#### **7.2.1Fault Symptoms for customers:**

Network Search.  
Handset drops calls.

#### **7.2.2Fault Symptom on GSM-Tester:**

Power problems on the internal antenna of the handset only.

### **7.3Priority:**

- ☐ ..... Mandatory
- ☐ ..... Repair
- ☐ ..... Optional
- ☐ ..... Not Yet Defined

**7.4 Repair Documentation****7.4.1 Description of procedure:**

The antenna spring connects the main board with the internal antenna of the handset.

**7.4.1.1 Diagnosis**

Visually check the status of the spring. Bent or oxidated springs have to be replaced.

**7.4.1.2 Repair by component change**

Use soldering iron to remove defective spring.  
Avoid excessive heat!  
Watch surrounding components!

Resolder new spring afterwards.

**7.4.1.3 Repair by SW-Booting**

Not possible!

**7.4.1.4 Test**

Retest handset after repair.

**7.4.2 List of needed material****7.4.2.1 Components**

Antenna Spring C10, C11  
Part-Number: L36158-A26-C430

**7.4.2.2 Jigs and Tools**

Hot Air Blower  
Soldering Iron

### 7.4.2.3 Special Tools

None

### 7.4.2.4 Working materials

Desolder Wick / Braid  
Solder

### 7.4.3 Drawings

Figure 1: C10 Board Antenna Spring Side




Figure 2: C10 Antenna Spring (X751) Placement (Top View)




Figure 3: C11 Board Antenna Spring Side






Figure 4: C11 Antenna Spring (X751) Placement (Top View)

