

Date 18.10.96	Ref. No. IP02696	Model CM-DX1000	TD
Subject Part number info: Ringer			IRIS

The **Ringer** has been made available under part number **1-759-063-11**.

NOTES

- When soldering the Ringer, care should be taken about the correct positioning, i.e. the Ringer's output should face the hole in the Upper Cosmetic correctly. Careless positioning may decrease the ringer level by several decibels.
- When the Ringer is not only soldered but also glued to the PCB, the ringer level will decrease due to the rigid contact between the Ringer and the PCB.