

Service Bulletin

| Date | Ref. No. | Model | TD |
|--------------------------------|----------|-----------|------|
| 09.05.96 | IP01096 | CM-DX1000 | |
| Subject | | | IRIS |
| Part number info: New Software | | | |

A new operating software has been issued for CM-DX1000. This software should be considered mandatory in view of the following improvements:

- Improved power management under weak network conditions (battery time when network connection is lost will not decrease quickly anymore).
- Improved hopping timing (when frequency hopping is used, connections in the past were sometimes lost due to critical timing).

Apart from these major improvements, minor points have been changed which are mainly not noticeable to users.

| Description | Part number | Languages |
|-------------|--------------|--|
| G1 | 9-948-000-03 | German, English, French, Italian, Dutch, Turkish |
| G2 | 9-948-000-02 | English, Danish, Swedish, Norwegian, Finnish, Dutch |
| G3 | 9-948-000-01 | English, Spanish, Portuguese, Hungarian, Greek, Zhong Wen Pin Vin (Chinese) |