

# **Product Service Group CE Audio**

# Service Information

Already published Service Informations:

#### **CORRECTION TO SERVICE MANUAL**

Front Page content:
The correct 3-CDC Module should be 3CDC-LLC-MCD1 instead of 3CDC-LLC-MB

## **CHANGES DURING PRODUCTION**

## **MMPWR 100W Module**

- \* From wk152 onwards a new Spring, Trans is introduced to clamp IC7257 (L7805CP) onto heatsink instead of direct screw mounting. This spring, Trans is available under service code: 4822 492 11735
- \* From wk218 onwards a new pt 5 Left/Right & Power Supply board is introduced due to additon of diode 6999 into same location as 9495. This change is for other set application & can be recognized by printing mark ....113\_34345\_01/...
- \* From wk218 onwards new Mains & Mains socket pc boards is introduced due to process improvement. The board can be recognized by printing mark ....3139 113 34822 01.

New pc board layout drawing is enclosed.

2000 - 06 - 03 3139 785 30073



