

Service Information

Domestic Appliances and Personal Care

1998-03-31

HI 510

HI 520

HI 530

HI 540

DAP160

Refer to Service Manual **4822 729 21818**

MODIFICATION 1

IRON : HI 510 only

Inlay pos. 6

Instead of 4822 310 11023 you now have to order 4822 310 11107.

MODIFICATION 2

IRON : HI 510, HI 520, HI 530 and HI 540

Control buttons pos. 7

To improve the functioning of the shot-of-steam and spray buttons (pos. 106 and 107), these buttons and the handle (pos. 15) have been redesigned. This change has been implemented with effect from week 9747.

For proper replacement of these components, proceed in the following way:

When produced before week 9747 : order 4822 310 11025

When produced after week 9747 : order 4822 310 11127

Handle pos. 15

When produced before week 9747 : also order a new set of control buttons
4822 310 11127.