SONY

Service Bulletin

Date	Ref. No.	Model	TD
31.05.96	**IP01296**	**CM-DX1000**	

Subject	IRIS
Phonelocking Detection	

With the latest software version dated 23.02.96 – announced in Service Bulletin IP01096 – it is possible to detect whether a set is phonelocked. The following procedure allows to find out whether a set is phonelocked.

- Make sure no SIM card is inserted.

- Power on.

- Dial *#06#. The set now shows the IMEI number (electronic identification).

- Push the softkey left. The set now shows the software date.

- Push the softkey left again, or, after performing the previous step, wait for approximately 10 s. The set now shows if it is locked or not. There are two possible locks, but for the customer they appear similar. Unlocking is similar.

NOTE

Phonelocking refers to a hardware lock of the set, not to any SIM card locking.

Sony Customer Relations & Service Europe
European Technical Support
Technologielaan 7
B - 1840 Londerzeel

1 / 1