

SONY

RGB/Video Monitors Service Bulletin

CSI-112

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: PVM-3230**No. 9****Subject:** Part Numbers for CP2301 to CP2318**Date:** January 21, 1994**Symptom:**

(***)

What are the Part Numbers to CP Modules 2301 through 2318 ?

Solution:

The Part Numbers to the CP Modules are listed Below:

PART No.	I-233-087-11	I-233-122-11
CP NO.	CP2301-CP2303 CP2306-CP2308 CP2311 CP2313-CP2315	CP2304 AND CP2305 CP2309 AND CP2310 CP2312 CP2316-CP2318
CIRCUIT DIAGRAMS	<p>2SA1175 (8-729-119-76)</p>	<p>2SC2785 (8-729-119-78)</p>

