

Service  
Service  
Service



Philips Domestic Appliances and Personal Care

# Service Manual

**HR 6949 is replaced by FC 8033**

**HR 6968 is replaced by FC 8034**

The active carbon in this filter absorbs unpleasant smells.

The two electrostatically charged filter layers make sure that the exhaust air is perfectly clean.

Replace this filter once a year or when you notice that its smell absorption becomes less effective.

**FC 8034** consists of: **FC 8033** = **4822 480 20145** Active Carbon filter  
and **4822 458 10461** Grille of this filter

This set can replace the motor inlet air filter mentioned in the Service Manuals

as items 12 and 13 for: **Mobilo** = HR 85xx

as items 41 and 42 for: **Vision** = HR 87xx  
HR 88xx  
HR 89xx

and

as items 9 and 10 for: **Universe** = FC 90xx and  
**Specialist** = FC 91xx

