

Service Information

1999-03-09

Solaria

DAP 202

Domestic Appliances and Personal Care

To avoid complaints about noise and vibrations in the appliance, we will from now on only supply complete fan assemblies, consisting of motor, fixing bracket and fan blade, according to the survey below:

HP3136 HB401 HB405 HB406 HB411

4822 361 10512	motor	- DELETED
4822 515 40178	fan blade	- DELETED
4822 361 11042	complete fan	- NEW

HB811 HB812 HB 814 HB815 HB 821 HB824

4822 361 21555	complete fan	- NO CHANGES
----------------	--------------	--------------

HP3701 HB850 HB851 HB853 HB861 HB863

4822 361 10512	motor	- DELETED
4822 515 40178	fan blade	- DELETED
4822 441 80678	fan housing	- DELETED
4822 361 11186	complete fan	- NEW

HB871 - up to production code 9829

4822 361 11041	complete fan floor part	- NO CHANGES
4822 361 11042	complete fan rad. parts	- NO CHANGES

HB871 - production code 9830 and higher

4822 361 11041	complete fan floor part	- NO CHANGES
4822 361 11042	complete fan rad. part inner section	- NO CHANGES
4822 361 11185	complete fan rad. part outer sections	- NEW