

# Service Information

Domestic Appliances and Personal Care

---

	1999-01-18
<b>HP 3701</b> <b>HB 850 / HB 851</b>	
	DAP 194

From production code 9836 onwards the microswitch SK4  
has been omitted.