

Date 05.06.98	Ref. No. <b>IP00298</b>	Model <b>CMD-Z1</b>	TD
Subject <b>Part number info: Screwdriver Bit</b>			IRIS

**SYMPTOM**

Removing the "Microphone Arm Assy" may be difficult, and/or correct reassembly cannot be performed as the screw is difficult to handle and to lock.

**CAUSE**

The screw which holds the "Microphone Arm Assy" is also locked with compound. When not using the correct screwdriver bit, incorrect torque will be applied so that the screw, the arm, and the holding part may be damaged.

**SOLUTION**

Use the correct type of "**Precision Screwdriver Bit**" (7-700-000-26).

**NOTE**

This screwdriver bit is to be used with the typical blue **Sony Screwdriver Handle** (7-721-051-03). The screwdriver bit mentioned above is finer than the bit which is usually delivered and used with this screwdriver handle.