

Date 21.11.97	Ref. No. IP01997	Model CMD-Z1	TD
Subject Clock Is Reset			IRIS 2171

SYMPTOM

Intermittently the clock is reset to 0.

CAUSE

Bad contacts between the Jog Board and the Main Board. Dust has clogged onto the contacts. This is related to temperature and moisture.

SOLUTION

Clean the contacts on both sides (Jog Board as well as Main Board) with alcohol. Make sure the contacts are dry before reassembling.

