

Service Information

1997-02-01

HD2003

DAP139

Domestic Appliances and Personal Care

Due to a modification in the **gearbox** and the **motor**, these parts of the /A and /B version are not interchangeable with the gearbox and the motor of the /C version and vice versa.

The spares are:

	version /A and /B	version /C	item
gear box assy	4822 522 20456	4822 522 10611	9
motor 230 V	4822 361 21724	4822 361 10956	11
motor 115 V	4822 361 10891	4822 361 10957	11
main cord - Japan	4822 321 11279		15

If you, however, use the gearbox and the motor of a particular version **together**, so as an assy, this assy can be used in all versions.