

# Service Service Service

Product Service Group CE Audio

# Service Information

*Already published Service Informations:*

## **MCU & CD BOARD CHANGES DURING PRODUCTION**

\*From production week 0330 onwards the MCU & CD board has been modified in order to eliminate the pink noise during CD playing.

Add IC1 5322 209 11548 MC74HC14AD

For servicing the new MCU & CD board, please refer to the attached pages.


## **OTHER CHANGE AND CORRECTION**

### **MCU & CD BOARD**


\*From production week 0330 onwards the following has been changed due to no need of video out.

Delete L1002 9965 000 19760 FIXED IND. 2.4UH /22/25


CIRCUIT DIAGRAM - MCU & CD BOARD  
Main Part



CIRCUIT DIAGRAM - MCU & CD BOARD  
MEPG Part



## LAYOUT DIAGRAM - MCU & CD BOARD COMPONENT SIDE



## LAYOUT DIAGRAM - MCU & CD BOARD SMD SIDE